NGW/KABOOT

	OMAN ENERGY ASSOCIATION Road Safety Standard	Document No: OPAL-STD-HSE-01 Rev 2 Issue Date: 01/07/2024

HEAVY VEHICLE

Service Code HV

Owner:	KABOOT INTERNATIONAL LLC	Vehicle Type and Model:	TIPPER (18Ton)
Current User:	"	Model Year	2017
Contact Number	-	Chassis Number:	WMA3W72SHM689206
Fleet Number:	-	Registration No:	4854-RH
Inspection Date:	03-08-2025	Registration Expiry Date	03-08-2026
Inspection Center:	UNITEC (NIMR)	Odometer Reading	116486 K.M.
MOT VOC Expiry date:	29-06-2026		

PART 1: CHECKLIST FOR INSPECTION

In Status column, enter ✓ - Pass x - Fail.
* = if required or applicable. Shaded box = according to contract or operational requirements.
Numbers in italics, in second column, refer to UK Dept. of Transport LGV Inspection Manual checkpoints.

S/N	UK HGV/LGV	DESCRIPTION	STATUS	DEFECT FOUND	RE-CHECKED
	1	**Brake**			
1	*34*	Pressure/Vacuum warning and Build Up	✓		
2	*36*	Hand Brake / Parking Brake / Mechanical brakes lever / Electronic Par brake	✓		
3	*37*	Service Brake Pedal	✓		
4	*38*	Service Brake Operation	✓		
5	*39*	Hand Operated brake control valves	✓		
6	*59*	Mechanical brake components	✓		
7	*60*	Brake actuators / Fail Safe Brake in all rear axles.	✓		
8	*4.5.13*	Dual-circuit, dual-line service brake system with an emergency braking system	✓		
9	*4.5.11*	All Vehicles must have vehicle retarder which may be an exhaust brake.	✓		
10	*61*	Brake system and components	✓		
11	*71*	Service brake performance. Decelerometer or roller brake tester printout attached to the form.	✓		
12	*72*	Secondary brake performance Decelerometer or roller brake tester printout attached to the form.	NA		
13	*73*	Parking brake performance Decelerometer or roller brake tester printout attached to the form.	NA		
	2	**Steering**			
14	*28*	Driving Controls	✓		
15	*30, 31, 32*	Steering wheel, column, Linkages, steering control.	✓		
16	*54, 55, 56*	Steering assembly including tie rod ends.	✓		
	3	**Visibility**			
17	*4.2.11.1*	Side view Mirrors / Look down mirror	✓		

18	4.2.11.2	must be equipped with a combination of 6 mirrors as a minimum	X		✓
19	23, 24	Windscreen for crack / vision / color in swept area	✓		
4		**Lamps. Reflectors and electrical equipment's**			
20	68	Headlamps	✓		
21	67	Headlamp aim	✓		
22	63, 64	Position lamps	✓		
23	66	Indicators	✓		
24	62	Rear markings	X		✓
25	65	Markers and Reflectors	✓		
26	69	Brake lights	✓		
27		Reversing lights	✓		
28	4.2.13	Reversing alarm for vehicles longer than	✓		
29	4.2.11.3	High-intensity rear lights (fitted with a 21watt bulb or an LED equivalent as a minimum)	✓		
30		Revolving lights	✓		
31	25	Windscreen wipers, washers	✓		
32	26	Speedometer	✓		
33	27	Horn	✓		
34	42	Electrical wiring and equipment	✓		
35		A/C unit	✓		
5		**Tyres, Wheels, Axles, and Suspensions**			
36	7	Check the tyre same manufacturer, type, size, speed rating, temperature rating (winter tyres are non-compliant), positional compliance (steering vs driving), take a photo of each tyre (ON/OFF Pattern)	✓		
37	8	Tyres condition and pressure (Max Life 4 years)	✓		
38	4.2.9.1	All Terrain' tyres are to be used on blacktop and graded roads	✓		
39	4.2.9.26	TPMS is mandatory for all vehicles	✓		
40	10	Spare wheels, Jack, Tools	✓		
41	6	Road wheels and hubs + Wheel nut indicator	✓		
42	48, 49, 50	Suspension / Leaf spring condition / Air suspension	✓		
43	51	Shock absorbers for leak/damage	✓		
44	53	Axles, Stub Axles, and wheel bearings	✓		
6		**Body, Structure, Power Transmission, and attachments**			
45	16	Cab doors + Signwriting	✓		
46	17	Cab floor and steps	✓		
47	4.2.11.5	Front & side windows not tinted or obscured	✓		
48	4.2.10.1	3-point inertia reel-type seatbelt and functionality.	✓		
49	18	Seats / Fire retardant seat covers	✓		
50	3.1	SRS- Supplementary Restraint Systems	✓		
51	4.5.1.2	*Rollover Side Curtain Airbag* for the driver and front passenger side	✓		

UNIQUE ENGINEERING TECHNICAL SERVICES LLC

52	9	Side guards, under-run guards, Rear bumper (500 mm) - UN/ECE R73	✓		
53	19, 20	Bodywork, load area, headboard fixed/ Condition of Body / Paint / Rust	✓		
54	4.5.8	Mudguards / Wheel Arches	✓		
55	15	Cab mountings	✓		
56	43	Engine, transmission mountings	✓		
57	41	Condition of Chassis, sub-frame	✓		
58	44	Oil leakages (Engine / Steering / Clutch / Transmission / Rear axle / Hydraulic etc.)	✓		
59		Fluid levels	✓		
60	45	Fuel tank(s) and systems / Leaks etc.	✓		
61	57	Transmission Operation	✓		
62	-	Prime Mover Access ladder & Platform	NA		
63	4.5.3	Maximum payload detail (in kg) of a cargo	✓		
64	4.2.8.12	ABS, EBS, ESC/RPS	✓		
65	4.5.10	Reflective yellow and black chevrons	✓		
	7	**Other Equipment**			
66		Fire extinguisher for cab	✓		
67		Fire extinguisher for load	✓		
68	4.2.12.2	Class A - First aid kit	✓		
69		Hazard Warning Triangles – 2 Nos	✓		
70	4.2.12.1	Wheel chocks – 2	✓		
71	4.2.8.2	Opal approved IVMS – Make / Serial No.	✓		
72		Speed limiter-by road-test + certificate	✓		
73	4.2.8.7	Working Music system operating	✓		
74	4.2.8.1	Maintain air conditioning system for maintaining cab temperature.	✓		
75	3.8.2	Fatigue and distraction detection devices	✓		
76	4.2.12.5	Minimum of one high visibility vests per occupant,	NA		
77	4.5.12	May be fitted with towing apparatus	NA		
78	4.2.8.3	No vehicle shall have a sunroof, any type of bull-bars, a seat which is sideways facing.	✓		
79		No green or blue lights	✓		
80	4.5.9	Storage box for tools and Auxiliary Equipment's	✓		
	8	**Miscellaneous items and Nuisance**			
81	5	Exhaust Smoke emission & MIL indicator	NA		
82	46	Exhaust System and Noise	✓		
83		Exhaust emission testing. Printout attached to the form.	NA		
84	4.2.8.14	Reverse assistance camera	NA		
85	4.2.7.2	All vehicles must be equipped with a spade, and Sand-boards (Jack spreader boards, for heavy vehicles)	✓		
86	4.2.7.3	All vehicles used on graded roads and off-road must have a minimum of ground clearance of 190 millimeters			

Sultanate of Oman
Nizar
C.R. No: 1570047
سلطنة عمان
نزر
TECHNICAL SERVICES LLC

		Vehicle Sub-category	Prime mover / Tractor Head		
87		Prime Mover Access Ladder & Platform			
88		Fifth wheel assembly on prime mover + certificate			
89		Security of attachment of fifth wheel to prime-mover chassis			
90	11	Trailer coupling – Color Coding			
91		Winch: General Condition			
92	4.5.4	Fitted with a metal grid catwalk between the rear of the cab and the 5th wheel, across the whole width of the vehicle			
93	4.5.15	Must have colour-coded palm couplings			
94	4.5.18	Must have a 5th wheel which oscillates only longitudinally.			
95	4.6.7	Fifth wheel NDT certificate			

		Vehicle Sub-category	Tipper		
96		Tippers: ram operation, oil leaks*	✓		
97		Tippers: hinge shaft and bearings*	✓		
98	4.7.2.1	Tippers: PTO interlock	✓		
99		Oilfield Headboard	✓		

		Vehicle Sub-category	Refrigerator		
100	4.2.8.14	Reverse assistance camera			

		Vehicle Sub-category	Hiab		
101		HIAB SWL & Inspection Date Stencil			
102	4.2.8.14	Reverse assistance camera			
103		Third-party inspection certificate			

		Vehicle Sub-category	Mobile crane		
104		HIAB SWL & Inspection Date Stencil			
105		Slings			
106		Third-party inspection certificate			
107		Swing Alaram for Rotating equipment			
108	4.2.8.14	Reverse assistance camera			
		Vehicle Sub-category	**Rigid Tanker**		
109		Centre of Gravity certificate for tankers			
110	4.2.8.14	Reverse assistance camera			
111	4.7.1.3	Tank color coding			
112	4.7.2.1	Vacuum Tankers: PTO interlock			
113	4.7.2.2	Water Tankers: Only diesel-operated Auxiliary engine.			
114	4.7.3.1	Tankers: Discharge control valve at the side of the trucks			

PART 2: DEFECT INFORMATION

In Check No. column, use the checklist number from the list above. Repairs to be signed off by the repair workshop supervisor.

If there are many defects, continue the blank page and attach to this report.

Check No.	Defect details	Action taken on Defect	Signed
1)	No lookdown mirror in front of codriverside,	New fitted	
2)	Tyre pressure marking missing	Done	

"I confirm that the above defects, if any were found, have been rectified satisfactorily. The vehicle is now in a proper roadworthy condition."

Name of Verifier

Ahmed

Signature of Verified

31/12/25

Name of Vehicle Inspector

Signature of Vehicle Inspector

05/01/2026

Serial No: BRK30874
S/W Version: 3.1.1

Company ID:
Easy Way First

Log memory: 1

Test Performed:
12:09:25 03/08/2025
Timezone: GMT (0000)

Service Brake Test

Front-Back Deceleration
Peak: 75 %g
Average: 51 %g
Left-Right Acceleration
Peak: 12 %g
Vehicle pulls: RIGHT
Test Speed: 39 km/h
Stopping Dist: 12.1 m
Brake Efficiency: 75 %
(Peak)

Calibration Ok
Due: 28/10/2025

TIPPER
Trailer ID

4851-RH
Vehicle Registration

BLACKTOP
Ground Condition

GOURAV
Inspector Name

Signature 03/08/2025

BrakeCheck

Serial No: BRK30874
S/W Version: 3.1.1

Company ID:
Easy Way First

Log memory: 1

Test Performed:
12:09:25 03/08/2025
Timezone: GMT (0000)

Service Brake Test

Front-Back Deceleration
Peak: 75 %g
Average: 51 %g
Left-Right Acceleration
Peak: 12 %g
Vehicle pulls: RIGHT
Test Speed: 39 km/h
Stopping Dist: 12.1 m
Brake Efficiency: 75 %
(Peak)

Calibration Ok
Due: 28/10/2025

TIPPER
Trailer ID

4851-RH
Vehicle Registration

BLACKTOP
Ground Condition

GOURAV
Inspector Name

Signature 03/08/2025